San Diego Unified School District - PPO

Page 1 of 1

Location ID: 091-1059-B123

Department:

Last Mod User: (

Signature:

Facility: Emerson Elementary Building: Portable 123 - Emerson

Address: 3510 Newton Ave San Diego, CA 92113

Description: Classroom - B123

Ph: Requester: 1 Account:

Sq Feet: 917.78 Ph: 619-344-6200

Closed

Printed On: 03/30/2017 12:54

Maximo #:

Work Type: Corrective Maintenance

Priority: High Project #: 26003

Requested: 01/26/2017 09:40

Closed: 02/02/2017 09:47

Est. Start: Est. End:

Est. Cost:

Supervisor:

Inspected By:

Hours: 16.75 2.30 Est. Hours:

Trade: Plumber

Job Code: A399 - Other Plumbing Issue

Status: Notified


Action Requested

Ref#: 298775

All of the bungalows 123-138 sink faucets the water is coming out with some kind of oil base substance.

01/26/2017 11:46 - Plumber dispatched. Safety officer has taken water sample.

01/26/2017 13:23 Plumber reports that water is milky then clears up, a sign of air in the line, but no oily substance. He will run hose bibs to bleed system. Water stations being delivered to site today.



Tech Report: 02/07/2017 09:40 - Open for late charges